COLORADO LAND SURVEY MONUMENT RECORD

Department of Regulatory Agencies
Board of Licensure for Architects, Professional Engineers and Professiona

on DECELVED
AUG 1 4 2018

1560 Broadway, Suite 1350


Denver, CO 80202

Phone: (303) 894-7800; Fax: (303) 984-2310; EMAIL: aes@dora.state.co.us; V/TDD 711


COLO. ST. BD. OF LIC

Report one monument only on this form - Reproduction of this form is authorized ARC, PE, AND PLS
All items are to be filled in by the Land Surveyor using **PERMANENT BLACK LETTERING** and lines which can be reproduced.

- 2. DESCRIPTION AND DATE OF MONUMENT FOUND:
 FOUND 3.25" BRASS CAP, PLS 23527, 2006, 0.5' BELOW RIM OF MONUMENT BOX.
 UNABLE TO VERIFY SIZE AND MATERIAL OF MONUMENT.
- 3. DESCRIPTION OF MONUMENT SET BY YOU TO PERPETUATE THE LOCATION OF THIS POINT: FOUND AND SET REFERENCE TIES AS SHOWN.
- 4. SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET. SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:



FOUND CENTER
OF MANHOLES ON
INLETS PER
MONUMENT
RECORD BY PLS
23519 FEBRUARY
28, 2013.



5. CERTIFICATION

This is to <u>certify</u> that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Name (Please Print): Peter E. Paulus
Firm Name: Lamp, Rynearson & Associates, Inc.

Firm Address: 4715 Innovation Drive, Fort Callins, CO 80525

Phone: (970) 226-0342

6. LOCATION DIAGRAM

Ga. Date of Field Work to Establish, Restore or Renabilitate
Manument: 4/24/2018

Date Monument was used as a Control Corner;
(Surveyor, do not fill in)

ACCEPTED


SEP 3 0 2018

COLO. ST. BD. OF LIC. FOR ARC, PE & PLS


RECEIVED AT OFFICE OF THE COUNTY CLERK
______COUNTY

BY: _____

Record to be filed numerically by Index Reference Number, then alphabetically by letter in the index reference number, then under appropriate Township, Range, and Meridian.



Location of Monument



Signature/Date through Seal

7.	SEC	36	_ T _	<u> 3</u> \$. R .	<u>66W</u>	<u>. </u>	6TH	P.M.
	COUN	:TY	ADAMS	<u>5</u> 1	OEX	REF	NUM	8ER	25-C

**8.	SEC	「 R, 6TH P.M.	
	COUNTY	INDEX REE NUMBER	

** To be used only for monuments located on county lines.



Rev. 02/01/2011

Engthering/0218003 XDG - Howkeys Nea 2018/SURVEY/MONUMENT RECORDS/135 REGM/SEC 36/E4.0mg PETE

COLORADO LAND SURVEY MONUMENT RECORDIS

Department of Regulatory Agencies

Doard of Licensure for Professional Engineers and Professional Land Surveyors


1560 Broadway, Suite 1350, Denver, CO 80202

I'hone (303) 894-7788 & Fax (303) 894-7790 & TTY Dial 711 for Relay Feborado MAY 0 3 2006

All items to be filled in by the Land Surveyor using PERMANENT BLACK LETTERING and lines which can be seen to be filled in by the Land Surveyor using PERMANENT BLACK LETTERING and lines which can be seen to be filled in by the Land Surveyor using PERMANENT BLACK LETTERING and lines which can be seen to be s


- 1. TYPE OF MONUMENT:

 SECTION CORNER
 QUARTER CORNER
 DBENCH MARK- --- D--OTHER ----
- 2. DESCRIPTION AND DATE OF MONUMENT FOUND: ON 04/27/06, FOUND NO. 6 REBAR W/21/2" ALMM. CAP, STAMPED AS SHOWN BELOW, O.6' BELOW ROAD SURFACE, IN RANGE BOX
- DESCRIPTION OF MONUMENT ESTABLISHED BY YOU TO PERPETUATE THE LOCATION OF THIS POINT:
- SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING



5.

7.




Stamping on Cap

Date of field Work to Establish, Restore or Rehabilitate
Monument:

-(Surveyor, do not fill in)-

Date Monument was used as a Control corner: (04.27-36 6.

This is to <u>certify</u> that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct. Name (Please Print): Rober Bully Ju Firm Name: WESTERN STATES SURVEYING, INC. Firm Address: 12753 SOUTH PARKER ROAD SUITE 205 PARKER, COLORADO 80134 Phone: (303) 841-7436 Crew: 5. Ha/pin
Date: 04/27/06 __ WSSI Point No.: /247 20507-001.4 _ WSSI Job No.:



RECEIVED AT OFFICE OF THE COUNTY CLERK

_ COUNTY

Record to be filed numerically by <u>Index Reference</u> <u>Number</u>, then elphabetically by letter in the index reference number, then under appropriate <u>Township</u> Range, and Meridian.

LOCATION DIAGRAM = 1 Mile

CERTIFICATION

6



= Location of Monument

hrough Seal nature/Date SEC 36 T 35 66W R COUNTY Adams INDEX REF NUMBER 23-E

**8.

COUNTY_

INDEX REF NUMBER_

.. To be used only for monuments located on county lines Rev.01/05

Nov 10, 2005

COLORADO LAND SURVEY MONUMENT RECORD

Department of Regulatory Agencies


Board of Registration for Professional Engineers and Professional Land Surveyors
1560 Broadway, Sulte 1370, Denver, CO 80202


Phone (303)894—7788 Fax (303)894—7790 V/TDD (303)894—7780

REPORT ONE MONUMENT ONLY ON THIS FORM — REPRODUCTION OF THIS FORM IS AUTHORIZED

All items to be filled in by the Land Surveyor using PERMANENT BLACK LETTERING and lines which can be reproduced

- 1. TYPE OF MONUMENT: M SECTION CORNER | QUARTER CORNER | BENCH MARK | OTHER_____
- 2. DESCRIPTION OF MONUMENT FOUND: Fnd 3" brass cap LS 16848 (City of Aurora) in box in concrete point referenced prior to E-470 construction — destroyed during that construction
- 3. DESCRIPTION OF MONUMENT ESTABLISHED BY YOU TO PERPETUATE THE LOCATION OF THIS POINT: Set 30" rebar w/ 3 1/4" alum cap stamped as shown below
- 4. SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET, SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:






a. Date of Field Work to Establish,Restore,Rehabilitate

Monument 5-18-99

b. Date Monument was Used as Control: N/A 281-054-768



CERTIFICATION

This is to <u>certify</u> that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Name (Please Print): Ronald E. IIk


Firm Name: MK Centennial Engineering

Firm Address: 10822 West Toller Drive

Phone: (303) 948-4001

6. LOCATION DIAGRAM 1" = 1 Mile

7.





**8. SEC___T____R___,__P.M.

COUNTY_____INDEX REF NUMBER_____

** To be used only for monuments located on county lines

h: \eng\isforms\monrec.doc (Rev.01/97)