

COLORADO LAND SURVEY MONUMENT RECORD


Department of Regulatory Agencies
 Board of Licensure for Architects, Professional Engineers and Professional Land Surveyors
 1560 Broadway, Suite 1350
 Denver, CO 80202
 Phone (303) 894-7800; Fax (303) 894-2310; EMAIL aes@dora.state.co.us; V/TDD 711

JUN 17 2015

Report one monument only on this form - Reproduction of this form is authorized by the Board of Lic. All items are to be filled in by the Land Surveyor using PERMANENT BLACK LETTERING and lines which can be reproduced.


1. TYPE OF MONUMENT: SECTION CORNER QUARTER CORNER SIXTEENTH CORNER OTHER _____
2. DESCRIPTION AND DATE OF MONUMENT FOUND: **FOUND 3/4" ALUMINUM CAP, INSIDE A CITY OF AURORA RANGE BOX. .8' BGLW RB LIO. FND ON 2-12-2015**
3. DESCRIPTION OF MONUMENT SET BY YOU TO PERPETUATE THE LOCATION OF THIS POINT:
NONE

4. SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET. SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:



- ① FND 3/4" ALUM. CAP (FND)
- ② PK NAIL N-SIDE PP
- ③ FND #5 REBAR FND #5 REBAR
- ④ WEST OF GAS LINE POST
- ⑤ FND #5 REBAR GAS LINE POST

5. CERTIFICATION
 This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.
 Name (Please Print): DENNIS E. HAMLIN
 Firm Name: DENVER INTL AIRPORT C.C.O.
 Firm Address: 8500 PEÑA BOULEVARD
DENVER, COLORADO 80249-6348
 Phone: 303-342-4428



- a. Date of field work to establish, restore or rehabilitate Monument: 2-12-2015
- b. Date Monument was used as a Control corner: _____

(Surveyor, do not fill in)

RECEIVED AT OFFICE OF THE COUNTY CLERK _____ COUNTY _____

BY: _____

DATE: _____

Record to be filed numerically by Index Reference Number, then alphabetically by letter in the index reference number, then under appropriate Township, Range, and Meridian.

6. LOCATION DIAGRAM
 1" = 1 Mile
-
- = Location of Monument
- Signature/Date through Seal
7. SEC 4 T 35 R 6SW 6TH P.M.
 COUNTY ADAMS INDEX REF NUMBER 9-X
- **8. SEC _____ T _____ R _____ P.M.
 COUNTY _____ INDEX REF NUMBER _____
- ** To be used only for monuments located on county lines



COLORADO LAND SURVEY MONUMENT RECORD

Department of Regulatory Agencies
 Board of Registration for Professional Engineers and Professional Land Surveyors
 1560 Broadway, Suite 1360, Denver, CO 80202
 Phone (303) 894-7788 • Fax (303) 894-7730 • TDD (303) 894-2300/2333


RECEIVED

APR 25 2007

COLO. ST. BD. OF LIC. FOR A.E.S.

REPORT ONE MONUMENT ONLY ON THIS FORM - REPRODUCTION OF THIS FORM IS AUTHORIZED BY THE BOARD OF REGISTRATION FOR PROFESSIONAL ENGINEERS AND PROFESSIONAL LAND SURVEYORS. THIS FORM IS TO BE FILLED IN BY THE LAND SURVEYOR USING PERMANENT BLACK LETTERING AND LINES WHICH CAN BE REPRODUCED.

1. TYPE OF MONUMENT: SECTION CORNER QUARTER CORNER BENCH MARK OTHER _____
2. DESCRIPTION OF MONUMENT FOUND:
FOUND 3 1/4" ALUMINUM CAP 0.8' BELOW SURFACE. SET RANGE BOX AND ORANGE CARSONITE POST.
3. DESCRIPTION OF MONUMENT ESTABLISHED BY YOU TO PERPETUATE THE LOCATION OF THIS POINT:
4. SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET, SHOW SUPPORTING AND/OR CONTRADICTIONARY EVIDENCE WHERE APPLICABLE:



5. CERTIFICATION

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Name (Please Print): JAN STERLING

Firm Name: CITY OF AURORA

Firm Address: 13645 E. ELLSWORTH AVE.
AURORA, COLORADO 80012

Phone: 303-326-8015

a. Date of field work to Establish, Restore or Rehabilitate Monument: MARCH 22, 2007

b. Date Monument was used as Control: _____

(Do not fill in)

ACCEPTED

MAY 24 2007


COLO. ST. BD. OF LIC. FOR A.E.S.

RECEIVED AT OFFICE OF THE COUNTY CLERK _____ COUNTY

BY: _____

DATE: _____

Record to be filed by Index Reference Number Numerically, then Alphabetically, under appropriate Township, Range, and Meridian.



7. SEC 9 T 3S R 65W 8TH P.M.

COUNTY ADAMS INDEX REF NUMBER 09-V

**8. SEC _____ T _____ R _____ P.M.

COUNTY _____ INDEX REF NUMBER _____

** To be used only for monuments located on county lines

Parcel Map Check Report

Client:

**Prepared
by:**

Date: 4/1/2020 1:57:43 PM

Parcel Name: Site 1 - 101

Description:

Process segment order counterclockwise: False

Enable mapcheck across chord: False

North: 724,401.3753'

East: 231,676.0914'

Segment# 1: Line

Course: S0° 28' 40"E

Length: 328.66'

North: 724,072.7268'

East: 231,678.8320'

Segment# 2: Line

Course: S66° 10' 01"W

Length: 14.64'

North: 724,066.8111'

East: 231,665.4404'

Segment# 3: Curve

Length: 220.63'

Radius: 465.00'

Delta: 27° 11' 09"

Tangent: 112.43'

Chord: 218.57'

Course: N37° 25' 33"W

Course In: S66° 10' 01"W

Course Out: N38° 58' 53"E

RP North: 723,878.9171'

East: 231,240.0925'

End North: 724,240.3850'

East: 231,532.6091'

Segment# 4: Line

Course: N51° 01' 07"W

Length: 105.37'

North: 724,306.6699'

East: 231,450.6997'

Segment# 5: Curve

Length: 97.17'

Radius: 955.00'

Delta: 5° 49' 48"

Tangent: 48.63'

Chord: 97.13'

Course: N14° 18' 55"W

Course In: N72° 46' 11"E

Course Out: S78° 35' 59"W

RP North: 724,589.5532'

East: 232,362.8412'

End North: 724,400.7859'

East: 231,426.6831'

Segment# 6: Line

Course: N89° 51' 50"E

North: 724,401.3784'

Length: 249.41'

East: 231,676.0924'

Perimeter: 1,015.89'

Error Closure: 0.0032

Error North : 0.00304

Area: 46,623.08Sq.Ft.

Course: N17° 45' 47"E

East: 0.00098

Precision 1: 317,462.50