

♀

MCLOSE VAC ROW.TXT  
 CHAMBERS ROAD EXCHANGE SUB FIL. NO. 2  
 MAPCOGO INPUT FILE: MCLOSE3.TXT  
 RUN DATE & TIME: 03/30/18 13:31  
 PAGE: 1

COGO MAPCHECK TRAVERSE FOR FIGURE 104 STORED IN PCG COGO TABLE: 98  
 \*VAC R/W /

POINT	BEARING	DISTANCE	NORTH	EAST
252			1704808.8243	3194625.3893
	S 0-21-10 W	45.20 FEET		
211			1704763.6251	3194625.1110
	N 89-38-50 W	15.00 FEET		
CC 268			1704763.7175	3194610.1113
	RADIUS = 15.00			
	DELTA = 90-44-22 LEFT			
	LENGTH = 23.76			
	TANGENT = 15.19			
	CHORD = 21.35			
	N 0-23-12 W	15.00 FEET		
210			1704778.7171	3194610.0101
	S 89-36-48 W	262.16 FEET		
209			1704776.9479	3194347.8560
	N 0-23-12 W	280.00 FEET		
CC 265			1705056.9416	3194345.9664
	RADIUS = 280.00			
	DELTA = 26-45-56 RIGHT			
	LENGTH = 130.80			
	TANGENT = 66.62			
	CHORD = 129.62			
	S 26-22-44 W	280.00 FEET		
208			1704806.0964	3194221.5610
	N 89-36-48 E	403.84 FEET		
252			1704808.8217	3194625.3918
CLOSING COURSE = N 44-48-47 W .004 CLOSURE ERROR = 1/366694				
AREA = 10926.44 SQUARE FEET .2508365 ACRES				

\*\*\*\*\*

♀